

## **NFMCF safety protocols for conventional (non-radioactive) materials work**

1. You may enter the “work area” only if you are wearing **all of the following**:
  - a. Long pants
  - b. Closed-toed shoes
  - c. Dosimeter badge
2. You may not eat food, drink beverages, chew gum, or apply makeup when you are in the “work area”.
  - a. You may do all these things in the “safe zone”.
3. To leave the “work area”, you must perform a 30 s full body portal scan and be verified free of any detectable contamination
  - a. You must do this **every time you wish to leave the work area**, even if just to enter the safe area briefly to eat and/or drink.
4. Any personal items you bring in to the “work area” with you (cell phone, tools, specimens, etc.) must be scanned using a frisker and be verified free of detectable contamination to leave the “work area”.
5. If contamination is detected on you and/or any of your personal items, you must remain in the “work area”, call the radiation safety officer (number posted on multiple yellow sheets in “work area”), and await further instructions.

## **NFMCF safety protocols for radioactive materials work**

1. All safety protocols indicated above for conventional materials work also apply for radioactive materials work.
2. To leave the “work area”, you must also scan the soles of your shoes with a frisker and verify these are free of detectable contamination; if any contamination is detected on the soles of your shoes, you must wait in the “work area” and contact the radiation safety officer and await further instructions as specified in #5 above for conventional materials work.